

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OCD Rec'd: 08/17/18

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report


Name of Company: XTO Energy OGRID: 5380	Contact: Kyle Littrell	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No: 432-221-7331	
Facility Name: Golden Child 6 State 1H	Facility Type: Exploration and Production	
Surface Owner: State	Mineral Owner: State	API No: 30-015-38544

LOCATION OF RELEASE

Unit Letter I	Section 6	Township 25S	Range 29E	Feet from the 2080	North/South Line South	Feet from the 990	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.157723 Longitude -104.018348 NAD83

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 11bbl	Volume Recovered 10bbl
Source of Release Tubing	Date and Hour of Occurrence 8/3/2018, 8:00 PM	Date and Hour of Discovery 8/3/2018, 8:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour: N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Crew had loaded tubing with water for pressure control and attempted to pull plug in profile nipple. Plug would not release. Crew had to pull tubing, which released fluid into cellar area of pad.		
Describe Area Affected and Cleanup Action Taken.* Fluid was contained to cellar area and caliche pad. Vacuum truck was dispatched and recovered 10bbl of standing fluid. An environmental contractor has been retained to assist with remediation.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kyle Littrell	Approved by Environmental Specialist: 	
Title: Environmental Coordinator	Approval Date: 08/18/18	Expiration Date: N/A
E-mail Address: Kyle.Littrell@xtoenergy.com	Conditions of Approval: N/A	Attached <input type="checkbox"/> 2RP-4927
Date: 8/17/2018 Phone: 432-221-7331		

* Attach Additional Sheets If Necessary

A#: pMAP1823047160

I#: nMAP1823047252