

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: LG&S Oil Company, LLC O#:257988	Contact: Louis Edgett
Address: P. O. Box 52, Lovington NM 88260	Telephone No. (575) 631-3387
Facility Name: Keohane B Federal central tank battery	Facility Type: central tank battery
Surface Owner: BLM	Mineral Owner: BLM
API No. 30-015-05625	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	28	18 S	31 E	1980	N	1980	W	Eddy

Latitude: **32.72030** Longitude: **-103.87700** NAD83

NATURE OF RELEASE

Type of Release: oil	Volume of Release: 50 bbl	Volume Recovered: 40 bbl
Source of Release: gun barrel	Date and Hour of Occurrence: ?	Date and Hour of Discovery: 8-16 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD called Louis Edgett, Louis called BLM 1300 8-16	
By Whom? NMOCD	Date and Hour: 8-16-18 ~0930	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Vandal opened gun barrel valve. Forty bbl recovered and run through gun barrel.

Describe Area Affected and Cleanup Action Taken.*

~35' x ~45' NW of battery. Forty bbl recovered. Laid down plastic sheet, oily dirt excavated & placed on sheet, hole backfilled with clean dirt, backfilled hole surrounded by barbed wire fence. Will fence oily dirt pile on plastic sheet. Will prepare remediation action plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Brian Wood	Approved by Environmental Specialist: 		
Title: Consultant	Approval Date: 08/23/18	Expiration Date: N/A	
E-mail Address: brian@permitswest.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 8-20-18 Phone: (505) 466-8120	N/A		2RP-4948

* Attach Additional Sheets If Necessary

A#: pMAP1823559766 I#: nMAP1823560032