

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAB1922139305
District RP	2RP-5567
Facility ID	
Application ID	pAB1922131667

77K0G-190729-C-1410

Release Notification

Responsible Party

Responsible Party Read & Stevens, Inc.	OGRID 18917
Contact Name Kelly Barajas	Contact Telephone 575-624-3760
Contact email kbarajas@read-stevens.com	Incident # (assigned by OCD) NAB1922139305
Contact mailing address PO Box 1518, Roswell, NM 88202	

Location of Release Source
 Latitude ****32.320914** NAD 83 ****AB** Longitude ****104.283330** **AB**
 (NAD 83 in decimal degrees to 5 decimal places)

Site Name Bandit State #1 SWD	Site Type SWD well
Date Release Discovered 7/27/2019	API# (if applicable) 30-015-21071

Unit Letter	Section	Township	Range	County
F	10	23S	26E	Eddy County, NM

Surface Owner: ☒ State ☐ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

☐ Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
☒ Produced Water	Volume Released (bbls) 75	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	☐ Yes ☐ No
☐ Condensate	Volume Released (bbls)	Volume Recovered (bbls)
☐ Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
☐ Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

One of the fitting valves had a leak.

State of New Mexico
Oil Conservation Division

Incident ID	NAB1922139305
District RP	2RP-5567
Facility ID	
Application ID	pAB1922131667

Was this a major release as defined by 19.15.29.7(A) NMAC?

☒ Yes ☐ No

If YES, for what reason(s) does the responsible party consider this a major release?

There was a 75 bbls of water released from one of the fittings from a leak.

If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?

By phone, spoke with Victoria Venegas at the OCD office in Eddy County at 9:28 AM on July 29, 2019. Followed up with 1 email stating the same.

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

- ☒ The source of the release has been stopped.
- ☒ The impacted area has been secured to protect human health and the environment.
- ☒ Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.
- ☐ All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:


Joe Tovar is in contact with Republic Backhoe Service to find out when they are available to recover the water and contaminated soil from the release.

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Kelly Barajas

Title: Production & Regulatory

Signature: 

Date: July 29, 2019

email: kbarajas@read-stevens.com

Telephone: 575-624-3760

OCD Only

Received by: Amalia Bustamante

Date: 8/9/2019