

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

AUG 23 2011

NMOCD ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

NMLB 1125153802

Release Notification and Corrective Action

*Tam R Cone (op of record - 188152)*

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	W/K Land Company	Contact	Carlos A de la Cruz
Address	911 Kimbark Street, Longmont, CO 80501	Telephone No.	(303) 442-0258
Facility Name	Southern California 14 Federal #1	Facility Type	Tank Battery

Surface Owner	Federal	Mineral Owner		Lease No.	API 3001504600
---------------	---------	---------------	--	-----------	----------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
11	14	19S	30E					Eddy

Latitude N 32.66138 Longitude W 103.93516

NATURE OF RELEASE

Type of Release	Oil	Volume of Release:	estimated 57 bbls	Volume Recovered	0 bbls
Source of Release	Oil tank	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	6/13/11 Discovered by BLM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A			

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*

Hole on bottom or side of oil tank. The remaining oil in the tank will removed to repair or replace tank.

Describe Area Affected and Cleanup Action Taken.\*

The spill area was contained inside the facility firewalls. The spill area will be scraped and sampled for evaluation. The excavated soil will be transported to proper disposal. Based on the NMOCD RRAI, either a work plan or a closure report will be submitted for review and approval.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rex Ross Walker</i>	OIL CONSERVATION DIVISION	
Printed Name Rex Ross Walker	Signed By <i>M. L. Brannan</i>	
Title: Managing Partner	Approved by District Supervisor:	
E-mail Address: cowboy@sombrero.com	Approval Date: SEP 08 2011	Expiration Date:
Date: 08/23/2011 Phone: 303-442-0258	Conditions of Approval: Remediation per OCD Rules & Guidelines. <b>SUBMIT REMEDIATION</b> <b>PROPOSAL NOT LATER THAN:</b> <i>10/8/2011</i>	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

*2RP-876*