

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-27734

Release Notification and Corrective Action

NMLB 1125755674

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company BOPCO, L.P.	260737	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 432-556-8730
Facility Name James Ranch Unit #41.		Facility Type E&P

Surface Owner State	Mineral Owner State	Lease No E5229
---------------------	---------------------	----------------

LOCATION OF RELEASE

Unit Letter N	Section 36	Township 22S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.343149 Longitude W 103.835467

NATURE OF RELEASE

Type of Release: Produced water and crude oil	Volume of Release: 15 bbls of produced water and 5 bbls of crude oil.	Volume Recovered: 10
Source of Release: Pumping well stuffing box.	Date and Hour of Occurrence 8/25/11, Hour unknown	Date and Hour of Discovery 8/17/11 9:30 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* The stuffing box packing failed, the packing was replaced the same day.

Describe Area Affected and Cleanup Action Taken.* Approximately 3000 sq. ft. of caliche well pad. All of the free liquid was removed with a vacuum truck and the saturated caliche was scraped up and stockpiled on-site. A remediation plan will be developed in accordance with the NMOCD remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by District Supervisor Signed By Mike Brannon	
Title: Waste Mgmt. & Remediation Specialist	Approval Date: SEP 14 2011	Expiration Date:
E-mail Address: TASavoie@BassPet.com	Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 10/14/2011	Attached <input type="checkbox"/>
Date: 9/11/11	Phone: 432-556-8730	

* Attach Additional Sheets If Necessary

2RP-902