API#: 30-015-39239

WELL NAME AND NUMBER Shrike 10 State Com No. 2H		
LOCATION Section 10, T25S, R28E, 400 FSL, 2490 FWL, Eddy County		
OPERATOR Lime Rock Resources		
DRILLING CONTRACTOR <u>Un</u>	ited Drilling, Inc.	
-	<u>-</u>	resentative of the drilling contractor
who drilled the above described well	l and had conducted deviation	test and obtained the following
results:		
Degrees @ Depth	Degrees @ Depth	Degrees @ Depth
0° @ 195'	91.3° @ 5046'	92.0° @ 5840'
3/4° @ 408'	91.3° @ 5078'	90.3° @ 6284'
2° @ 863'	91.0° @ 5110'	87.9° @ 6346'
3 1/2° @, 989'	91.2° @ 5174'	91.0° @, 6410'
3° @ 1176'	92.1° @ 5205'	90.0° @ 6315′
2 3/4° @ 1302'	92.9° @ 5237'	90.5° @ 6378'
1 1/2° @ 1522'	94.2° @ 5395'	91.0° @ 6442'
3/4° @ 1805'	93.5° @ 5427'	91.5° @ 6505'
3/4° @, 2338'	35.5° @ 5459'	
1 3/4° @ 2622'	92.4° @ 5491'	
1 3/4° @ 2748'	91.8° @ 5522'	RECEIVED
1 3/4° @ 2999'	90.8° @ 5554'	
3/4° @ 3218'	91.4° @ 5713'	SEP 09 2011
1/2° @ 3501'	92.7° @ 5744'	- APTESIA
1/4° @ 4035'	93.1° @ 5776'	NMOCD ARTESIA
91.3° @ 5014'	92.4° @ 5808'	
	Drilling Contractor-	UNITED DRILLING, INC.
By: Xuna Jonega		
(Luísa Norlega)		
Title: Assistant Office Manager		
0.5. 9.1.1	. 1 c anth .	2.1
Subscribed and sworn to before me this 30th day of August, 2011.		
(1 M2 7.		
		Culue I fulle
		Coline Mallic Notary Public Chaus New Mexico
	/o./	Chaves Theolyes
My Commission Expires: ///	8/17	County State
1-10/10		