

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

11123835522 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company SM ENERGY COMPANY 154903	Contact VICKIE MARTINEZ
Address 3300 N "A" ST BLDG 7-200 MIDLAND, TX 79705	Telephone No. (432)688-1709
Facility Name PARKWAY 36 STATE #001	Facility Type BATTERY
Surface Owner COMMISSIONER OF PUBLIC LANDS	Owner COMMISSIONER OF PUBLIC LANDS
Case No. 30-015-26112	

LOCATION OF RELEASE

Unit Letter F	Section 36	Township 19S	Range 29E	Feet from the North/South Line	Feet from the East/West Line	County EDDY
------------------	---------------	-----------------	--------------	-----------------------------------	---------------------------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

C-141 entered under wrong API number. See 30-015-25671/

Type of Release PRODUCED WATER	Volume of Release 125	Volume Recovered 0
Source of Release UNKNOWN	Date and Hour of Occurrence 8/9/11	Date and Hour of Discovery 8/9/11
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	By Whom? BILL HEARNE	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Date and Hour _____ If YES, Volume Impacting _____	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

AUG 15 2011

NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.*

SOMETIME BETWEEN 8/8/11 AND 8/9/11 AN UNKNOWN WATER TRANSPORT TRUCK BACKED UP TO LOCATION AND DUMPED A LOAD IN PASTURE NEAR SM ENERGY'S PARKWAY 36 STATE #001

Describe Area Affected and Cleanup Action Taken.*

AFFECTED AREA - PASTURE LAND 36'X126' WHICH EQUALLED 7938 SQ FT AREA
CLEAN UP ACTION TAKEN - NO WATER RECOVERED AND WILL TURN OVER TO TETRA TECH ENVIRONMENTAL FOR ASSESSMENT AND CLEAN UP

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Vickie Martinez	OIL CONSERVATION DIVISION	
Printed Name: VICKIE MARTINEZ	Signed By: [Signature] Approved by District Supervisor:	
Title: ENGINEER TECH II	Approval Date: AUG 26 2011	Expiration Date:
E-mail Address: VMARTINEZ@SM-ENERGY.COM	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 08/10/2011 Phone: (432)688-1709	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 9/26/2011	

* Attach Additional Sheets If Necessary

2RP-865