

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO.  
30-15-24531-00-00

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
LH-2392

7. Lease Name or Unit Agreement Name  
State DU SWD

8. Well Number 1

9. OGRID Number 138987

10. Pool name or Wildcat  
Herradura Deleware

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☐ SWD RECEIVED

2. Name of Operator  
MWS Producing, Inc.

MAR 30 2005

3. Address of Operator  
P.O. Box 1404, Stanton, TX 79782

OCU-ARTESIA

4. Well Location

Unit Letter F : 1673 feet from the North line and 1980 feet from the West line  
Section 36 Township 22s Range 27e NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water

Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

03/23/2005

RU well service unit, RU wireline truck, ran "F" plug to profile nipple, ND wellhead, RU BOP unlatch on-off tool. Pulled 6' sub and replaced. Latched on to on-off tool landed tubing w/ 6pts tension. ND BOP and flanged up wellhead. PSI casing annulus to 600 psi charted 30 minutes held OK. PSI tubing and retrieved "F" plug. RD wireline, well service unit and put well back on injection.

No Pit

Chart Attached

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Michael W. Swinson TITLE President DATE 03/29/2005

Type or print name Michael W. Swinson E-mail address: mwsprod@msn.com  
For State Use Only

Telephone No. 432.756.2902

Accepted for record - NMOCD

APPROVED BY: TITLE

Conditions of Approval (if any):

MAR 31 2005

