District I
1625 N. French Dr., Hobbs. NM 88240
District II
1301 W. Grand Avenue, Artesia. NM 88210
District III
1000 Rio Brazos Road, Aztec. NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe. NM 87505

State of New Mexico Energy Minerals and Natural Resources

JAN 0 7 2005 OCD-ARTESIA

RECEIVED

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

30-015-31255

Release Notification and Corrective Action

ml\$0509050402						OPERATOR				M Initia	al Report		Final Repor	
Name of Company HARVEY E YATES COMPANY			Y	Contact	Jei	n Atkins	on							
Address PO BOX 1933						Telephone ?	No. (5	05)623-6	601					
Facility Name TURNER 7 FEDERAL #1						Facility Typ	e O	IL TAN	<u>K</u>					
Surface Owner FEDERAL Mineral Owner										Lease No. NMLC-063567				
				LOCA	TIO	N OF RE	LEASI	Ē						
Unit Letter	etter Section Township Range Feet from the No			th/South Line Feet from the East/				West Line County						
E	7	20 S	27 E	1980'	N	orth	66	0' V		est Eddy				
	LatitudeLongitude													
				NAT	URE	OF REL								
Type of Release Major							Volume of Release 34 Bbls Volume Recovered None							
Source of Rel Tank Valve	Date and Hour of Occurrence Unknown				Date and Hour of Discovery 1/1/2005 at 6:30 am									
Was Immedia	If YES, To Whom?							-						
☐ Yes ☑ No ☐ Not Required							No - over the New Year holiday							
By Whom? Was a Watercourse Reached?							Date and Hour							
was a watero	If YES, Volume Impacting the Watercourse. n/a													
If a Watercou	rse was Im	pacted, Descri	ibe Fully.*			<u> </u>		**						
n/a Describe Cause of Problem and Remedial Action Taken.* Roswell WM														
Describe Cause of Problem and Remedial Action Taken.* Roswell Wm														
Tank valve broken on oil tank. Has been repaired as of Jan. 4, 2005. 8211-/933														
Describe Are	Describe Area Affected and Cleanup Action Taken.*													
Oil leaked into the protective dike around the tank, which is plastic lined and completely contained. There was dirt and gravel in the dike, and all of the oil was completely soaked up and/or evaporated in the dike. Oil non-recoverable.														
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.														
	OIL CONSERVATION DIVISION													
Signature: S		TIM GUM												
Printed Name: Jeanetta Atkinson						Approved by District Supervisor:								
Title: Prod A	Analyst		·			Approval Dat	e: 3/3	165		Expiration 1	Date: ~/			
E-mail Address: jatkinson@hevco.org						Conditions of Approval:				Attached				
Date: 1/4/0				505.623.6601				MlA	+					
Attach Addit	ional Shee	ete If Necess												