


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

Release Notification and Corrective Action

nMLB 1133942446 OPERATOR ☒ Initial Report ☐ Final Report  
Name of Company: Linn Operating 269324 Contact: Joe Hernandez  
Address: 2130 W. Bender Hobbs, NM 88240 Telephone No.: 575-738-1739  
Facility Name: Skelly Unit # 134 Facility Type: Production  
Surface Owner: BLM Mineral Owner: BLM API No.: 3001522268

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	27	17S	31E	1860	N	660	W	Eddy

Latitude: 32 51' 3.6" Longitude: 103 52' 3.8"

NATURE OF RELEASE



Type of Release: Oil / Water	Volume of Release: 18 / 1	Volume Recovered: 15 / 0
Source of Release: Poly flowline	Date and Hour of Occurrence: 11/18/2011 1:30pm	Date and Hour of Discovery: 11/18/2011 2:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher - NM OCD / Terry Gregston - BLM	
By Whom? Joe Hernandez	Date and Hour 11/22/2011 11:30am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*:

Describe Cause of Problem and Remedial Action Taken.\*: 3" poly flowline popped at fuse

Describe Area Affected and Cleanup Action Taken.\* : Vaccum truck picked up standing fluid. Further remedial action pending.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Joe Hernandez	Signed By  Approved by District Supervisor	
Title: Production Foreman	DEC 05 2011 Approval Date:	Expiration Date:
E-mail Address: jhernandez@linenergy.com Date: 11/28/2011 Phone: 575-942-9492	Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 1/5/2012	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

2 RP- 966