District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 RECEIVED

Form C-141 Revised October 10, 2003

MAR 13 2012 Revised October 10, 2003
Submit 2 Copies to appropriate
Submit 2 Copies to appropriate with Rule 116 on back side of form

## **Release Notification and Corrective Action**

nMLB 120	83497	oz				OPERA?	TOR		OPERATOR Initial Report Final Re					
Name of Company Apache Corporation 873						Contact Natalie Gladden								
Address PO Box 1849 Eunice, NM 88231						Telephone No. 575-390-4186								
Facility Name Lee Federal #3						Facility Type Production Well								
Surface Owner BLM Mineral Owner						BLM Lease No. 30-015-30269						59		
				LOCA	ATIO	N OF REI	LEASE							
Unit Letter	Section	Township	Feet from the		South Line	Feet from the	East/We	st Line	County					
) <sub>T</sub>	20	178	31E	1700'	FSL		990'	FEL	FEL Eddy					
I	] 20	173	<u></u>	L	ITSL	T amaited	<u> </u>	FEL		Lady		<del> </del>		
	Latitude Longitude Longitude													
m cn.i	NATURE OF RELEASE  Type of Release Oil and Produced Water Volume of Release 15 Volume Recovered 10													
Type of Release Oil and Produced Water Source of Release Stuffing Box leak						<del></del>								
Source of Release Stuffing Box leak						Date and Hour of Occurrence Date and Hour of Discovery 2/26/12					У			
Was Immediate Notice Given?						If YES, To Whom?								
☐ Yes ☒ No ☐ Not Required														
By Whom? Natalie Gladden						Date and Hour 2/27/12 9am								
Was a Water	course Reac		No		If YES, Volume Impacting the Watercourse.									
If a Watercou	ena ruga Im							<del></del>	<del></del>					
ii a watercou	use was iiii	pacieu, Descii	ibe runy.											
Describe Cau	Describe Cause of Problem and Remedial Action Taken.*													
BLM was out	BLM was out doing inspections when the stuffing box leak was found. Fluid was recovered.													
												•		
Describe Area				en.* I cleared, then the	site wil	l he remediate	ed to NMOCD St	andards						
Sile was back	uraggou un	in one-can is j	piaced and	cicarca, aich aic	SILC WII	i oc icinogian	ed to MMOCD St	മാവമാധം.				,		
												i		
I hereby certif	y that the in	nformation giv	ven above	is true and comple	ete to th	e best of my	knowledge and ur	nderstand	that purs	uant to NMC	OCD :	rules and		
regulations all	operators	are required to	report an	d/or file certain re	lease no	tifications an	d perform correct	ive action	s for rele	ases which r	may e	endanger		
public health	or the envir	onment. The	acceptanc	e of a C-141 repor	rt by the	NMOCD ma	rked as "Final Re	port" doe	s not reli	eve the opera	ator o	of liability		
				investigate and re ance of a C-141 re										
federal, state,					oport de	os not reneve	uic operator or it	сэронэни	ity for co	miphance wi		y outci		
$\bigcap$ $A$						OIL CONSERVATION DIVISION								
Signature: Other (200den														
						Approved by District Supervisor.								
Printed Name:	Natalie G	ladden				-pproved by I		··	ħ	-				
Title: EHS Environmental Tech						Approval DateIAR 2 3 2012 Expiration Date:								
E mail Addas	a. matalia a	laddar@araa												
E-mail Address: natalie.gladden@apachecorp.com					in ation nor ULD Naice				Attached					
Date: 2/27/12 Phone: 575-390-4186						Remediation per OCD No.								
TOPOSAL NOT LATER ITALY									- > /1	/				
PROPOSAL NOT LATER THAN:  2012  2012										- 1064				
						1/4	<u> </u>			-		<i>i</i> = /		