

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

MLB/216755873

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company BOPCO, L.P.	<u>260737</u>	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 432-556-8730
Facility Name Poker Lake Unit Well #241		Facility Type E&P

Surface Owner Federal	Mineral Owner Federal	Lease No. <u>APZ#</u>
-----------------------	-----------------------	-----------------------

LOCATION OF RELEASE

30-015-34308

Unit Letter O	Section 30	Township 24S	Range 30E	Feet from the <u>840</u>	North/South Line <u>South</u>	Feet from the <u>2030</u>	East/West Line <u>East</u>	County Eddy
------------------	---------------	-----------------	--------------	-----------------------------	----------------------------------	------------------------------	-------------------------------	----------------

Latitude N 32.18333 Longitude W 103.91900

NATURE OF RELEASE

Type of Release: Produced water and crude oil	Volume of Release: 7 Bbls of Produced water and 2 Bbls crude oil	Volume Recovered: None
Source of Release: 2 7/8" flow line	Date and Hour of Occurrence 5/23/12 Time unknown	Date and Hour of Discovery 5/23/12 3:46 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* The flow line developed a leak due to external corrosion. One joint of pipe was replaced.

Describe Area Affected and Cleanup Action Taken.* Approximately 420 sq. ft. of pasture land. All of the released fluid soaked into the ground. The spill location is right on the south edge of the well pad, it appears to be near the reclaimed drill pit location. The remediation will comply with the NMOCD and BLM requirements for spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tony Savoie</u>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by District Supervisor Signed By <u>[Signature]</u>	
Title: Waste Mgmt. & Remediation Specialist	Approval Date: <u>JUN 15 2012</u>	Expiration Date:
E-mail Address: TASavoie@BassPet.com	Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 7/15/2012	Attached <input type="checkbox"/>
Date: 6/4/12	Phone: 432-556-8730	

* Attach Additional Sheets If Necessary

RECEIVED
JUN 12 2012
NMOCD ARTESIA

2RP-1173