District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

\* Attach Additional Sheets If Necessary

## State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

2RP-1141

Release Notification and Corrective Action											
nMLB/2/5334891						OPERATOR   Initial Report   Final Report					
						Contact Tony Savoie					
						Telephone No. 432-556-8730					
Facility Name: James Ranch Unit #112-H Pumping Well						Facility Type E&P					
Surface Owner: State of N.M. , Mineral Owner S						State of N.M. Lease No. NM 02953-C					
LOCATION OF RELEASE AP 30-015-36722											
Unit Letter P	it Letter   Section   Township   Range   Feet from the   North/				h/South Line	Feet from	the Ea	ast/West Line	County Eddy		
Latitude 32.34270 Longitude W 103.82626											
NATURE OF RELEASE  Yellows (Pales of Conde cil and are dised under a Walnut and a Walnut a Research 10 blue total fluid											
Type of Release: Crude oil and produced water							Volume of Release: 15 bbls crude oil and 15 bbls produced water  Volume Recovered: 10 bbls total fluid				
Source of Release: Pump Jack Well Head						Date and F	Iour of Occume unknown	ccurrence Date and Hour of Discovery			
Was Immediate Notice Given?  ☐ Yes ☐ No ☐ Not Réquired						If YES, To Whom? NMOCD Emergency # 104					
By Whom? Tony Savoie						Date and Hour 4/30/12 2:49 p.m.					
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.				
☐ Yes ⊠ No							RECEIVED				
If a Watercourse was Impacted, Describe Fully.*										MAY 04 2012 NMOCD ARTESIA	
Describe Cause of Problem and Remedial Action Taken.* The well pressured up and blew out the stuffing box packing. The packing was replaced and the pressure problem was corrected.											
Describe Area Affected and Cleanup Action Taken.*An area covering approximately 1800 sq.ft. on the caliche well pad was affected by the release. All of the free standing fluid was recovered with a vacuum truck. The stained area on the well pad was left intact; a remediation crew will start sampling the impacted area on 5/7/12 to determine the vertical extent of the release. The spill will be remediated following the NMOCD guidelines for spill remediation. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other											
federal, state, or local laws and/or regulations.											
Signature: Cua Zaura A						Approved by District Supervisor / Semance					
Title: Waste Mgmt. & Remediation Specialist Approval Date:  Approval Date:  Expiration Date:									Date:		
E-mail Address: TASavoie@BassPet.com  Co  Date: 5/2/12 Phone:432-556-8730							Conditions of Approval:  Remediation per OCD Rules &  Attached				
Date: 5/2/12 Phone:432-556-8730 Attach Additional Sheets If Necessary  Guidelines. SUBMIT REMEDIATION											

PROPOSAL NOT LATER THAN: