

Susana Martinez

Governor

John Bemis
Cabinet Secretary-Designate

Brett F. Woods, Ph.D. Deputy Cabinet Secretary Jami Bailey
Division Director
Oil Conservation Division



Date 4/16/12

API # 30-0 15 - 39 713

Dear Operator:

I have this date performed a Mechanical Integrity Test on the ND 19 (1904AL)

X If this test was successful the original chart has been retained by the NMOCD and will be scanned into the well's file in 7 to 10 days, pending receipt of the Form C-103 indicating the reason for this test. The well files are located at www.emnrd.state.nm.us/ocd/OCDOnline.htm

If this test was unsuccessful the original chart has been returned to the operator pending repair and retest of the well, which must be accomplished within 90 days. If this is a test of a repaired well, previously in non-compliance, all dates and requirements of the original non-compliance are still in effect. No expectation of extension should be construed as a result of this test.

___ If this test was for Temporary Abandonment include in your detailed description, on Form C-103, the location of the CIBP and any other tubular goods in the well, as well as your request for TA status.

If this is a successful test of a repaired well you must submit a form C-103 to NMOCD within 30 days. This C-103 must include a <u>detailed</u> description of the repair to the well. Only after receipt of the C-103 will the non-compliance be closed.

Let this is a successful Initial Test of an injection well you must submit a form C-103 to NMOCD within 30 days. This C-103 must include a <u>detailed</u> description of the work done on this well including the position of the packer, tubing information and the date you began injection into the well.

If I can be of additional service contact me at (575) 748-1283 ext 107.

Thank You,

Richard Inge Field Inspector District II - Artesia

KutALD INGE

Oil Conservation Division 811 S. First Street • Artesia, New Mexico 88210 Phone (575)748-1283 • Fax (575) 748-9720 • www.emnrd.state.nm.us/OCD



