

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUN 21 2012
NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

nJMW 1217353333 OPERATOR Initial Report Final Report

Name of Company: Linn Operating 269324	Contact: Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Skelly # 93	Facility Type: Injection

Surface Owner: Federal	Mineral Owner: Federal	API No.: 3011504885
------------------------	------------------------	---------------------

LOCATION OF RELEASE

30-015-04885

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	28	17S	31E	1980	North	1980	West	Eddy

Latitude: 32.8073812700173 Longitude: -103.876798708408


NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 50	Volume Recovered: 25
Source of Release: Pipeline	Date and Hour of Occurrence: 06/12/2012 3:30pm	Date and Hour of Discovery: 06/12/2012 4pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher-NM OCD Terry Gregston-BLM	
By Whom? Joe Hernandez	Date and Hour 06/13/2012 12:30pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*:		

Describe Cause of Problem and Remedial Action Taken.*: Crew working for Blaze was digging trench and struck a 2" fiberglass line. Shut in at header and contained line.

Describe Area Affected and Cleanup Action Taken.*: Leak stayed in ditch that was dug. Crew doing work was TNT. Called Alliance Trucking to pickup water in trench. Further remedial action pending...

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Joe Hernandez	Approved by District Supervisor: Signed By 	
Title: Production Foreman	Approval Date: JUN 21 2012	Expiration Date:
E-mail Address: jhernandez@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 06/21/2012 Phone: 575-942-9492		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**

7/21/12

2RP-1187