

RECEIVED

JUL 13 2012

District I
1625 N. French Dr., Hobbs, NM 88240
District II **NMOCD ARTESIA**
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 122125040

OPERATOR☒ Initial Report ☐ Final Report

Name of Company - Legacy Reserves Operating, LP 240974	Contact: Berry Johnson
Address - PO box 10848, Midland, TX 79702-7848	Telephone No. : 432-689-5200
Facility Name - South Red Lake II Unit #37	Facility Type: WIW

Surface Owner:	Mineral Owner: Federal	Lease No. API # 30-015-00715
----------------	------------------------	------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	1	18S	27E	330'	North	330'	West	Eddy

Latitude 32.78253 N Longitude -104.23978 W**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release 4-5 bbls	Volume Recovered -0- bbls
Source of Release : 2" steel line	Date and Hour of Occurrence 6/25/2012	Date and Hour of Discovery 6/25/2012
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

There was a leak at the 2" steel line that feeds injection well. No water was recovered, the well was shut in, the line was repaired and brought back into service.

Describe Area Affected and Cleanup Action Taken.* The affected area was about 30' X 50' just east and south of the well. There was a small amount of mist that settled northeast of the location. Tilon/LPE has been contracted to complete site assessment and work plan activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Sharon Bowersock</u>	OIL CONSERVATION DIVISION	
Printed Name: Sharon Bowersock	Approved by District Supervisor: Signed By <u>Mike Bowersock</u>	
Title: Eng./Regulatory Tech	Approval Date: <u>JUL 30 2012</u>	Expiration Date:
E-mail Address: sbowersock@legacylp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 07/13/2012 Phone: (432) 689-5200		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

8/30/12

2RP-1231