

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1219345739 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company BOPCO, L.P. <i>260737</i>	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730
Facility Name: Poker Lake Unit Delaware C SWD Battery	Facility Type E&P

Surface Owner Federal	Mineral Owner Federal	Lease No 891000303F <i>API-4</i>
-----------------------	-----------------------	----------------------------------

Poker Lake Unit #153 **LOCATION OF RELEASE** *30-015-31412*

Unit Letter G	Section 6	Township 24S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.248850 Longitude W 103.919067

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 25 bbls of produced water	Volume Recovered: None
Source of Release: Produced water storage tank	Date and Hour of Occurrence 5/30/12, Hour unknown	Date and Hour of Discovery 5/30/12 8:30 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Emergency #104 and Jim Amos with the BLM	
By Whom? Tony Savoie	Date and Hour 6/1/12, NMOCD at 11:41 a.m. BLM at 11:45 a.m. The report was delayed due to a medical situation with T.S.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A pipe fitting on the discharge line from the SWD pump broke, the pipe connection was replaced the same day.

Describe Area Affected and Cleanup Action Taken.. Approximately 1960 sq.ft. of pasture land was impacted west of the tank battery, this area has had several flow line spills in the same area that the release covered. All of the fluid soaked into the ground before it could be recovered. A remediation plan will be developed in accordance with the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by District Supervisor: Signed By <i>Mike Brennan</i>	
Title: Waste Mgmt. & Remediation Specialist		Approval Date: JUL 11 2012	Expiration Date:
E-mail Address: TASavoie@BassPet.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/24/12	Phone: 432-556-8730		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

8/11/12

**2RP-1205
RECEIVED
JUN 26 2012
NMOCD ARTESIA**