


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
2 Copies to appropriate
Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW1219549113 OPERATOR ☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Grave Digger State Com #3H Tank Battery	Facility Type	Tank Battery

Surface Owner	State	Mineral Owner		Lease No.	(API#) 30-015-39151
				Closest well location	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
2	2	20S	25E					Eddy

Latitude 32 36.545 - Longitude 104 27.171

NATURE OF RELEASE

Type of Release	Produced fluids	Volume of Release	50bbls oil 50bbls produced water	Volume Recovered	49bbls oil 49bbls produced water
Source of Release	gasket on separator man-way plate	Date and Hour of Occurrence	06/22/2012	Date and Hour of Discovery	06/22/2012 9:00 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD		
By Whom?	Michelle Mullins	Date and Hour	06/22/2012 4:40 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A failed gasket on separator allowed for the release of fluid inside the lined facility. The gasket has been replaced on the separator.

Describe Area Affected and Cleanup Action Taken.*

Initially 100bbls of fluid were released from the separator and we were able to recover 98bbls with a vacuum truck. All free fluid from the release was picked up from inside the lined facility. We have removed contaminated gravel and replaced with fresh gravel. The facility has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Approved by District Supervisor.	Signed By
Title:	HSE Coordinator	Approval Date:	EXPIRATION DATE:
E-mail Address:	jrusso@conchoresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	07/12/2012	Phone:	432-212-2399

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:

8/13/12

2RP-1226