RECEIVED

<u>District I</u> 1625 N French Dr , Hobbs, NM 88240 District II 1301 W Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

OCT **05** 2012

Form C-141 Revised October 10, 2003

Oil Conservation Division 1220 South St. Francis Dr.

NMOCDnARTESIAn repriate District Office in hce with 19.15.29 NMAC

Release Notification and Corrective Action OPERATOR Initial Report Final Report Name of Company: Linn Operating 269324 Contact: Joe Hernandez Address: 2130 W. Bender Hobbs, NM 88240 Telephone No.: 575-738-1739 Facility Name: Skelly Unit # 93 Facility Type: Injection Surface Owner: Federal Mineral Owner: Federal API No.: 3001504885 LOCATION OF RELEASE Feet from the North/South Line Feet from the East/West Line Unit Letter Section Township Range North 1980 F 28 17S 31E 1980 West Eddy

Santa Fe, NM 87505

Latitude: 32.8073812700173 Longitude: -103.876798708408

NAT	UKE	OF	KELEASE	_
		Ve	lume of Release	2bbls /

Type of Release: Oil / Produced Water	Volume of Release: 2bbls / 10bbls	Volume Recovered: 0 / 0			
Source of Release: 2" Fiberglass injection line	Date and Hour of Occurrence: 09/27/2012 11:30am	Date and Hour of Discovery: 09/27/2012 12:00			
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required	If YES, To Whom? M. Bratcher- NM OCD Terry Gregston-BLM				
By Whom? Gary Wink	Date and Hour 10/02/2012 3:45pm				
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.				
If a Watercourse was Impacted, Describe Fully.*:					
Describe Cause of Problem and Remedial Action Taken.*: bird electric was digging holes in ground for power poles and hit underground 2" fiber glass					
injection line that was marked. Etech has assessed the spill, took samples. Further remedial and cleanup action pending.					
Describe Area Affected and Cleanup Action Taken.*: 80yd south of well head. Spot 15'x20'.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
141 8	VATION DIVISION				
Signature: Ask Charles A					
Printed Name: Joe Hernandez	signed By Mile Benevice				
Title: Production Foreman	Approval Date: Expiration Date:				
Date: 10/05/2012 Phone: 575-942-9492	Conditions of Approval:	Attached			
Attach Additional Sheets If Necessary	Remediation per OCD Ru	les & 2RP-1327			

Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: