


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit to appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

nJMW/228449908

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating 269324	Contact: Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Skelly Unit # 18	Facility Type: Injection

Surface Owner: Federal	Mineral Owner: Federal	API No.: 3001505154
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	15	17S	31E	660	North	660	West	Eddy

Latitude: 32.8400142033788 Longitude: -103.864017185541

NATURE OF RELEASE


Type of Release: Produced Water	Volume of Release: 15bbbls	Volume Recovered: 0
Source of Release: injection line	Date and Hour of Occurrence: 09/11/2012 11am	Date and Hour of Discovery: 09/11/2012 11:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher-NM OCD Terry Gregston-BLM	
By Whom? Gary Wink	Date and Hour 09/13/2012 10am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: Dixie was digging ditch to lay conduit for COG & hit 2" fiber glass injection line coming from Skelly Unit # 18, S.I. inj header stop leak.

Describe Area Affected and Cleanup Action Taken.*: spill was on COG loc. Area affected 75' x 15'. Further remedial action pending.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Joe Hernandez	Approved by District Supervisor:		
Title: Production Foreman	Approval Date:	Expiration Date:	
E-mail Address: jhernandez@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 09/19/2012 Phone: 575-942-9492			

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:

Nov. 10, 2012

2RP-1309