

1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

RECEIVED

SEP 14 2012

Oil Conservation Division
2040 South Pacheco
Santa Fe, NM 87505

Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

NMOC D ARTESIA

Release Notification and Corrective Action

Name of Company <i>Kersey & Company 12576</i>		Contact <i>Kenneth Wade</i>	
Address <i>P.O. Box 1248, Fredericksburg Tx</i>		Telephone No. <i>830 992-9588</i>	
Facility Name <i>Texaco State C.K</i>		Facility Type <i>Tank Battery</i>	

Surface Owner <i>State of N.M.</i>	Mineral Owner <i>State of N.M.</i>	Lease No. <i>E9222</i>
---------------------------------------	---------------------------------------	---------------------------

New Mexico *CH* State *NOT* LOCATION OF RELEASE *API# 30-01505709*

Unit Letter <i>E</i>	Section <i>36</i>	Township <i>18S</i>	Range <i>31E</i>	Feet from the <i>1650</i>	North/South Line	Feet from the <i>330</i>	East/West Line	County <i>Eddy</i>
-------------------------	----------------------	------------------------	---------------------	------------------------------	------------------	-----------------------------	----------------	-----------------------

NATURE OF RELEASE

Type of Release <i>Oil</i>	Volume of Release <i>80 bbls</i>	Volume Recovered <i>0</i>
Source of Release <i>Production Tank</i>	Date and Hour of Occurrence <i>un known</i>	Date and Hour of Discovery <i>Aug 27</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? <i>K. Wade</i>	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Someone shot a hole in the side of production tank with what appears to be a large caliber bullet

Describe Area Affected and Cleanup Action Taken.*

Release was to both sides of tank battery, approximately 10ft x 50 ft on North and 30ft x 100 ft on South. Since no waterway or fresh water is found in area are working area and spraying with Microblaze

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kenneth R Wade</i>		OIL CONSERVATION DIVISION	
Printed Name: <i>Kenneth R Wade</i>		Approved by District Supervisor:	Signed By <i>Mike Brown</i>
Title: <i>Owner</i>	Approval Date: <i>09-10-2012</i>	Expiration Date:	
Date: <i>09-08-12</i>	Phone: <i>830 992-9588</i>	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:

Nov. 10, 2012

2RP-1308

Tank Battery Texaco State CK

