


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

njm 1228937789

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd. <i>16696</i>	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	Sand Dunes 28 Federal #1 SWD	Facility Type	Salt Water Disposal

Surface Owner	BLM	Mineral Owner		Lease No.	API#30-015-26194
---------------	-----	---------------	--	-----------	------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	28	23S	31E	1980'	South	1980'	East	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	2 bbls oil / 370 bbls water	Volume Recovered	2 bbls oil / 340 bbls water
Source of Release	Tank overflow due to pump failure from short in alarm system	Date and Hour of Occurrence	09/08/2012 @ 8:00 am	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	James Amos- BLM, Mike Bratcher- OCD		
By Whom?	Chancey Summers	Date and Hour	9/10/2012 @ 9:55 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A weather storm caused the alarm to short out and the pump to fail which made the tank overflow. 2 bbls of oil and 370 bbls of water leaked onto the ground. 2 bbls of oil and 340 bbls of water were recovered via vacuum truck.

Describe Area Affected and Cleanup Action Taken.*

The area affected was on location approximately 100' x 100' and in the pasture approximately 3' x 200'. Remediation will be performed in accordance with an OCD and BLM approved remediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:			
Printed Name:	Chancey Summers	Approved by District Supervisor:	Signed By <i>Mike Bratcher</i>
Title:	Sr. HES Specialist	Approval Date:	OCT 15 2012
E-mail Address:	Chancey.Summers@oxy.com	Expiration Date:	
Date:	Phone: (575)397-8216	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**
Nov. 15th 2012

2RP-1319