


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

TMW 1228934070 OPERATOR ☒ Initial Report ☐ Final Report
Name of Company Oxy Permian Ltd. 16696 Contact CJ Summers
Address 1017 W. Stanolind Rd, Hobbs, NM Telephone No. (575) 397-8216
Facility Name Cedar Canyon 28 Federal #4 Facility Type Gathering

Surface Owner BLM Mineral Owner Lease No. NM 94651

LOCATION OF RELEASE

API: 30-015-29118

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	28	24S	29E	1980'	South	1950'	West	Eddy

Latitude N 32.18629° Longitude W 103.99155°

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 80 bbls	Volume Recovered 0 bbls
Source of Release Valve on suction line left open	Date and Hour of Occurrence 08/14/2012	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher- OCD; James Amos- BLM	
By Whom? Chancey Summers	Date and Hour 08/14/2012 @ 12:58 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The valve on a 1" steel suction line between the triplex pump and tank was left open which caused 80 bbls of water to spill onto the ground. 0 bbls of water were recovered. The valve was closed to prevent further leaking.

Describe Area Affected and Cleanup Action Taken.*

The area affected by the 80 bbls leak is approximately 40' x 100'. Remediation will be performed in accordance with an OCD and BLM approved remediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Chancey Summers

Title: HES Specialist

E-mail Address: Chancey.Summers@oxy.com

Date: 9/25/12

Phone: (575) 397-8216

Approved by District Supervisor: Signed By Mike Bratcher

OCT 15 2012

Approval Date:

Expiration Date:

Conditions of Approval:

Attached ☐

* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:

Nov. 15, 2012

2RP-1318