


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

nJMW 1229729836

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Cimarex Energy	162683	Contact SWD	Terry D. Ainsworth
Address	600 Marienfeld Midland, TX 79701		Telephone No.	(575) 390-1388
Facility Name	Liberty 24 FC 1 SWD		Facility Type	Salt Water Disposal

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

#### LOCATION OF RELEASE

API - 30-015-33094

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	24	25S	26E	1650	North	1200	West	Eddy

Latitude 32 07' 04.91" N Longitude 104 15' 01.86"

#### NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	25 BBLS	Volume Recovered	24 BBLS
Source of Release	Discharge side of injection pump	Date and Hour of Occurrence	10/11/2012 7AM	Date and Hour of Discovery	10/11/2012 8AM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The piping between the injection pumps had another leak.  
We dug it up and temporarily repaired.

Describe Area Affected and Cleanup Action Taken.\*

It covered an area of approximately 40' x 40'. We had a vacuum truck pick up what we could. Backhoe to back drag.  
We are already waiting on a game plan to present to BLM to clean up this location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Terry D. Ainsworth		Approved by District Supervisor Signed By <i>M. H. [Signature]</i>	
Title: Production Foreman		Approval Date: OCT 23 2012 Expiration Date:	
E-mail Address: tainsworth@cimarex.com		Conditions of Approval:	
Date: 10/11/2012 Phone: 575-390-1388		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules &  
Guidelines. SUBMIT REMEDIATION  
PROPOSAL NOT LATER THAN:

November 23, 2012

ZRP-1331