Form 3160-5 (November 1994)

W.M. Oil Cons. DIV-Dist. 2

UNITED STATES 1301 W. Grand Avenue

DEPARTMENT OF THE INTERIOR

A COLOR DIVIDINAL SOCIETY.

| LOKM WL | KUYED |
|--------------|---|
| OMB No. | MM4.0135 |
| | |
| Expires July | , 21 1006 |
| Dybuce seri | , ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, |

| | | BUREAU OF LAND MAN | | | a, l | NM 882 | | | | |
|--|---|--|---------|-------------------------------|---|----------------------------------|-----------------------------|---------------------|--------------------|---------------------------------------|
| SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. | | | | | NMNM100331 6. If Indian, Allottee or Tribe Name | | | | | |
| | | RIPLICATE - Other Instr | ucti | ons on reverse | side H | ÉCEIVED | 7. If Unit | or CA | /Agreement, Name | ind/or No. |
| 1. Type of We | ill I 🖾 Gas Well (| Other | | | 1 | AUG 1 7 2005 | 8. Well N | Iame a | nd No. | · · · · · · · · · · · · · · · · · · · |
| 2. Name of O | perator | | | | | U-MATER | | | leral No. 1 | |
| | roleum Manag | gement Co. | | | | | ₫ | | | |
| 3a. Address P. O. Box 140907 Irving, TX 75014-0907 | | | 36 | Phone No. (include 972-401-31 | 30-015-33101 10. Field and Pool, or Exploratory Area | | | | | |
| 4. Location of | Well (Footage, Sec | c., T., R., M., or Survey Description | n) | <u> </u> | | | Burton | Flat; | Morrow | |
| SHL: 125 | 50' FNL & 2170 | 0' FWL Sec. 7-T21S-R27 | E | | | | 11. County or Parish, State | | | |
| BHL: 125 | 50' FNL & 159 | 2' FWL Sec. 7-T21S-R27 | E | | | | Eddy C | o., N | M | |
| | 12. CHECK A | PPROPRIATE BOX(ES) T | O IN | DICATE NATU | RE O | F NOTICE, R | EPORT, C | R O | THER DATA | |
| TYPE OF S | UBMISSION | | | TY | PE O | F ACTION | | | | |
| Notice of | | Acidize | | Deepen | | Production (Star | /Resume) | 0 | Water Shut-Off | |
| <u> </u> | intent | Alter Casing | | Fracture Treat | | Reclamation | - | | Well Integrity | |
| Subsequer | ıt Report | Casing Repair | | New Construction | | Recomplete | | \boxtimes | Other Set surface | <u>:e</u> |
| Final Abar | ndonment Notice | Change Plans | | Plug and Abandon | | Temporarily Ab | andon | andon casing | | |
| | | Convert to Injection | | Plug Back | <u>u</u> | Water Disposal | | | | |
| testing has b | een completed. Fi hat the site is ready Spudded we | volved operations. If the operational Abandonment Notices shall for final inspection.) 11. 3-3/8" 48# H-40 STC cases | be file | d only after all requi | iremen | nts, including recla | amation, hav | e been | completed, and the | operator has |
| | Seal + 10# G | + 10# Gilsonite + 1/2# Flocele + 2% CaCl and 445sx Premium Plus + 2% CaCl + 4% Bentonite + 1/4# | | | | | | | | |
| | Flocele. Tail | . Tail cemented with 250sx Premium Plus + 2% CaCl. Ran temperature survey and found TOC at 360'. | | | | | | | | |
| | One-inched | One-inched to 360' using 50sx Premium Plus + 3% CaCl. | | | | | | | | |
| 07-18-05 | 07-18-05 One-inched to 195' using 200sx Premium Plus Neat + 2% CaCl. One-inched to 120' using 100sx Premium | | | | | | | | um | |
| Plus Neat + 3% CaCl. One-inched to 105' using 100sx Premium Plus Neat + 3% CaCl. | | | | | | | | | | |
| Circulated 13sx to surface. Tested casing to | | | | to 500psi. WO | 500psi. WOC 40.5 hrs. | | | ACCEPTED FOR RECORD | | |
| | | | | | | | ACOLI | | | |
| | | | | | | | | AUG | 1 5 2005 | |
| I hereby certify that the foregoing is true and correct Name (Printed/Typed) | | Title | Title | | | LES BABYAK PETROLEUM ENGINEER | | | | |
| Natalie K | rueger | | | Regu | lator | y Technician | PEI | KUL. | C (119) 1.1 (C) | |
| Signature | talie B | nuoge | | Date Aug | ust 3 | 3, 2005 | | | | |
| | | - 71 | OR | FEDERAL OR S | TATE | OFFICE USE | | | | |
| approved by | | | | | tle | | | Date | | |
| | | attached. Approval of this notice | | | ffice | · · | 1 | | | |
| | | l or equitable title to those right conduct operations thereon. | ıs in t | ne subject lease | | | | | | |