

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-20341

Release Notification and Corrective Action

NMLB0525950563

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Devon Energy Production Co. LP	Contact: Jennifer Van Curen
Address: PO Box 250; Artesia, NM 88211	Telephone No.: 505-748-0160
Facility Name: Todd 36 State 1	Facility Type: Battery

Surface Owner	Mineral Owner	Lease No. K-952
---------------	---------------	-----------------

LOCATION OF RELEASE

Unit Letter K	Section 36	Township 23S	Range 31E	Feet from the 1980	North/South Line NORTH	Feet from the 1980	East/West Line WEST	County EDDY
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: water	Volume of Release: 2000	Volume Recovered: 1800
Source of Release: Valve on disposal well had a hole in valve body	Date and Hour of Occurrence 8:00 pm 8-19-05	Date and Hour of Discovery 8:00 pm 8-19-05
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Joe Hawkes at NMOCD	
By Whom? Joe Huber	Date and Hour: 8-19-05 at 9:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED

RECEIVED

SEP - 7 2005

SEP - 7 2005

OCD-ARTESIA

OCD-ARTESIA

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Hole in valve appears to a manufacturing defect. Built berm to control the spill. Called vacuum trucks to pick up standing water. Changed out valve on wellhead using a valve from a different manufacturer and style.

Describe Area Affected and Cleanup Action Taken.*

Spill stayed on location. Hauled contaminated soil to CRI (disposal)

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jennifer Van Curen</i>		OIL CONSERVATION DIVISION	
Printed Name: Jennifer Van Curen		Approved by District Supervisor: TIM GUM by MB <i>M/G Bencher</i>	
Title: Production Field Tech		Approval Date: 9/16/05	Expiration Date: N/A
E-mail Address: Jennifer.vancuren@dv.com		Conditions of Approval:	
Date: 9-5-05 Phone: 748-0160		Attached <input checked="" type="checkbox"/>	

* Attach Additional Sheets If Necessary



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Devon Energy Production Co. LP
PO Box 250
Artesia, NM 88211-0250

September 16, 2005

Re: Todd 36 State 001 K-36-23s-31e 30-015-20341 Incident # nMLB0525950563

The New Mexico Oil Conservation Division District II Office is in receipt of an Initial Report C-141 reporting a produced fluids release that occurred on 8/19/2005 at or near the above referenced well site.

Please submit a Corrective Action Work Plan to this office for correction/remediation of this release. Please use the "Guidelines For Remediation of Leaks, Spills, and Releases" as your guide.

This document may be found on the NMOCD web site: www.emnrd.state.nm.us/ocd , under Publications/Environmental Handbook/Miscellaneous Guidelines/Spill Prevention Clean up.

The work plan presented to the NMOCD must include general site characteristics, site ranking score, soil remediation action levels, soil remediation methods, and planned analytical testing for TPH, B-TEX , Chlorides or any other CoCs as applicable.

A final Form C-141 is required for closure of the release incident and must include a report of remediation actions taken with final analytical results attached.

BLM approval required if applicable.

Please have the requested work plan in the Artesia office on or before September 30, 2005. The NMOCD District II Office must be notified 24 hours prior to any remediation actions and/or subsequent soil samples taken for analysis.

In the event that a satisfactory response is not received to this letter further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe. Such a hearing may result in imposition of **CIVIL PENALTIES** for your violation of NMOCD rules.

If I can be of assistance in this matter, my contact information is listed below.

Mike Bratcher
NMOCD District 2
1301 W. Grand Ave.
Artesia, NM 88210
(505) 748-1283 Ext. 108
(505) 626-0857
mbratcher@state.nm.com