

# RECEIVED

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

JAN 15 2013

NMOCD ARTESIA

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

nJMW1302332891

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company *Range operating 227588*

Contact *Rod Garcia*

Address

Telephone No. *575-706-9132*

Facility Name *South Culebra Bluff 2-B Lease*

Facility Type *Flowline*

Surface Owner

Mineral Owner

API No.

## LOCATION OF RELEASE

*\*30-015-22591*

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>0</i>	<i>14</i>	<i>23S</i>	<i>28E</i>	<i>N/A</i>	<i>N/A</i>	<i>N/A</i>	<i>N/A</i>	<i>Cddy</i>

Latitude

Longitude

## NATURE OF RELEASE

Type of Release <i>Produced water / BS</i>	Volume of Release <i>20-30 BBL</i>	Volume Recovered <i>0</i>
Source of Release <i>Flowline in pasture</i>	Date and Hour of Occurrence <i>12.29</i>	Date and Hour of Discovery <i>12.29 3:00 p.m.</i>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? <i>Jacob Melancon</i>	Date and Hour <i>1.3.2013</i>	<i>2:30 p.m.</i>
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

*N/A*

Describe Cause of Problem and Remedial Action Taken.\*

*Flowline in pasture began to leak causing 20-30 BBL of produced water and B.S. to flow onto ground. No fluid was standing in pasture, backhoe began cleaning up pasture area by scraping and stock piling.*

Describe Area Affected and Cleanup Action Taken.\*

*Pasture area northeast of Reid Wells #1, took equipment to location dug out and hauled visible contamination to disposal*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

## OIL CONSERVATION DIVISION

Signature

*Rod Garcia*

Printed Name:

*Rod Garcia*

Approved by Environmental Specialist:

Signed By

*Mike Benson*

Title:

*Production Supervisor I*

Approval Date:

*JAN 23 2013*

Expiration Date:

E-mail Address:

*rgarcia@range-resources.com*

Conditions of Approval:

Attached ☐

Date: *12-31-2012*

Phone: *575-706-9132*

Remediation per OCD Rule & Guidelines. **SUBMIT REMEDIATION**

PROPOSAL NO LATER THAN:

*Feb. 23, 2013*

*2RP-1517*

\* Attach Additional Sheets If Necessary