

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JAN 02 2013

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

07M/1302230992

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company 217817	Contact Ron Robinson
Address 3300 North A St. Bldg 6, Midland Tx. 79705-5406	Telephone No. 575-390-4923
Facility Name: James E Upper Battery	Facility Type Oil And Gas

Surface Owner: BLM	Mineral Owner: Federal Government	Lease No. 0479142
--------------------	-----------------------------------	-------------------

LOCATION OF RELEASE

30-015-26645

Unit Letter E	Section 12	Township 22S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy County
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	-----------------------

Latitude 32.40849

Longitude 103.9480

NATURE OF RELEASE

Type of Release: Hydrocarbon produced water & oil	Volume of Release: 18bbbls oil/5bbbls produced water	Volume Recovered: 16bbbls oil/4bbbls water
Source of Release: Overflow/tank	Date and Hour of Occurrence 12-29-12 10:10 am MST	Date and Hour of Discovery 12-29-12 10:45 am MST
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Air line freeze up causing production equipment to fail/overflowing separator into blow down tank. Isolated by operator trucks called in to pick up fluids.		
Describe Area Affected and Cleanup Action Taken.* Effectuated dike area around facility and 210'x 15' of pasture ground.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: Ron Robinson

Printed Name: Ron Robinson

Title: Lead HSE

E-mail Address: ron.e.robinson@conocophillips.com

Date: 12-31-2012 Phone: 575-390-4923

Approved by District Supervisor: Signed By Mike Benavides

Approval Date: JAN 22 2013

Expiration Date:

Conditions of Approval:

Remediation per OCD Rule &
Guidelines. SUBMIT REMEDIATION

Attached ☐

PROPOSAL NO LATER THAN:

February 22, 2013

2RP-1509

* Attach Additional Sheets If Necessary