


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

nJMW1302234481

OPERATOR

☐ Initial Report ☐ Final Report

Name of Company: Chevron USA 4323	Contact: Amy Barnhill
Address: 2401 Avenue O Eunice, NM 88231	Telephone No.: 432-940-8524
Facility Name: Lentini I Federal Battery	Facility Type: Tank Battery

Surface Owner: BLM	Mineral Owner: BLM	API No. 30-015-27535
--------------------	--------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	1	23	28					Eddy

Latitude: 32.33380 Longitude: -104.04287

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 46.925 Bbls	Volume Recovered: 30 Bbls
Source of Release: Flowline	Date and Hour of Occurrence: 12-1-12	Date and Hour of Discovery: 12-1-12 @ 8:50am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Called 575-393-6161 E.L. Gonzales	
By Whom? Amy Barnhill	Date and Hour: 12-2-12 @ 11:00am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Pin hole in pipe body. Switched valves so flow stopped. Called vacuum truck to pick up fluid.		
Describe Area Affected and Cleanup Action Taken.* .75' x 27' x 156'. Vacuum truck picked up 30 Bbls of BS & W. Further remediation will be performed in accordance with a NMOCD approved remediation plan.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Amy Barnhill

Title: HE Specialist

E-mail Address: ABarnhill@chevron.com

Date: 12-2-2012

Phone: 432-940-8524

Approved by Environmental Specialist:

Signed By *Mike Barnhill*

JAN 22 2013

Approval Date:

Expiration Date:

Conditions of Approval:

Remediation per OCD Rule &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NO LATER THAN:**

February 27, 2013

Attached ☐

2RP-1510

* Attach Additional Sheets If Necessary