

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

JAN 08 2013

Submit 1 Copy to appropriate District Office in  
conformance with 19.15.29 NMAC

Form C-141  
Revised October 10, 2003

### Release Notification and Corrective Action

NJM 1301738512

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating 269324	Contact: Jose Hernandez
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Skelly 402	Facility Type: Oil Producer

Surface Owner: Federal	Mineral Owner: Federal	API No.: 3001529860
------------------------	------------------------	---------------------

#### LOCATION OF RELEASE

Unit Letter E	Section 28	Township 17S	Range 31E	Feet from the 2625	North/South Line North	Feet from the 230	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude: 32.8056025220413 Longitude: -103.882515126919

#### NATURE OF RELEASE

Type of Release: Oil / Produced water	Volume of Release: 4 bbls / 2 bbls	Volume Recovered: 0 / 0
Source of Release: 3" Polyline	Date and Hour of Occurrence: 12/21/2012 3pm	Date and Hour of Discovery: 12/21/2012 3:30pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher - NM OCD Terry Gregston- BLM	
By Whom? Gary Wink	Date and Hour 01/04/2013 9:15am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	


If a Watercourse was Impacted, Describe Fully.\*:

Describe Cause of Problem and Remedial Action Taken.\*: Both of leaks were caused by scale in 3" poly line

Describe Area Affected and Cleanup Action Taken.\* : 1st spill, about 2ft wide, by 30ft long on the edge of well pad oil and water were soaked up by sand 2nd spill about 200 yards east from first spill was about 3ft wide by about 6ft long soaked up in sand of a right away that was made by bird elect.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

#### OIL CONSERVATION DIVISION

Signature: 

Printed Name: Joe Hernandez

Title: Production Foreman

E-mail Address: jhernandez@linenergy.com

Date: 01/08/2013

Phone: 575-942-9492

Approved by District Supervisor:

Signed By 

Approval Date:

JAN 17 2013

Expiration Date:

Conditions of Approval:

Attached ☐

Remediation per OCD Rules &  
Guidelines. SUBMIT REMEDIATION  
PROPOSAL NOT LATER THAN:

February 17, 2013

2RP-1501

\* Attach Additional Sheets If Necessary