

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JAN 17 2013

Form C-141
Revised October 10, 2003

NMOCD ARTESIA
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

Operator ☒ Initial Report ☐ Final Report

Name of Company Oxy Permian Ltd. **Contact** Christopher Jones
Address 1502 W. Commerce Dr., Carlsbad, NM **Telephone No.** (575) 628-4121
Facility Name Old Ranch Knoll 8 Federal #7 **Facility Type**

Surface Owner BLM **Mineral Owner** **Lease No.** API#30-015-32621

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	8	22S	24E	1790	North	2170	East	Eddy County, NM

Latitude N 32.40715° Longitude W 104.51900


NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	20 bbls	Volume Recovered	0 bbls
Source of Release	Water dump line at Victaulic clamp froze and broke	Date and Hour of Occurrence	1/15/13	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher- OCD, James Amos-BLM, Terry Gregston-BLM		
By Whom?	Christopher Jones	Date and Hour	1/16/13 @ 7:13 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* A water dump line at the victaulic clamp froze and broke causing 20 bbls of produced water to leak onto the ground. 0 bbls were recovered and the line was repaired.					
Describe Area Affected and Cleanup Action Taken.* The area affected is approximately 100' x 40'. A water dump line at the victaulic clamp froze and broke causing 20 bbls of produced water to leak onto the ground. Fluids were not recoverable. Remediation will be performed in accordance with an OCD and BLM approved remediation plan.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

OIL CONSERVATION DIVISION

Signature: 

Printed Name: Christopher Jones

Approved by District Supervisor: Signed By 

Title: HES Specialist

Approval Date: JAN 23 2013

Expiration Date:

E-mail Address: Christopher.Jones@oxy.com

Conditions of Approval:

Remediation per OCD Rule & Guidelines. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN:**

Date: 1/17/13 Phone: (575) 628-4121

Attached ☐

* Attach Additional Sheets If Necessary

Feb. 23, 2013

2RP-1521