

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JAN 08 2013

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW1301740270

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Dodd Federal Unit 15A	Facility Type	Tank Battery

Surface Owner	Federal	Mineral Owner		Lease No. (API#)	30-015-35139
				Closest well location	

(Dodd Fed un. #110 API)

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	15	17S	29E					Eddy

Latitude 32 49.680 Longitude 104 03.470

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	43bbls	Volume Recovered	40bbls
Source of Release	Oil tank	Date and Hour of Occurrence	12/25/2012	Date and Hour of Discovery	12/25/2012 5:00 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher -OCD		
By Whom?	Michelle Mullins	Date and Hour	12/25/2012 7:35 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The wrong equalizer valve was open causing fluid to run into a full tank. The correct equalizer valve has been opened.

Describe Area Affected and Cleanup Action Taken.*

Initially 43bbls of oil were released from the oil tank into the lined facility and we were able to recover 40bbls with a vacuum truck. All free fluid has been recovered and the tank battery vessels have been cleaned. Any contaminated gravel has been removed from the tank battery and we have replaced fresh gravel into the tank battery as necessary. The facility has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name: Josh Russo

Title: Senior Environmental Coordinator

E-mail Address: jrusso@concho.com

Date: 01/07/2013 Phone: 432-212-2399

OIL CONSERVATION DIVISION

Approved by District Supervisor:

Signed By

Approval Date: JAN 17 2013

Expiration Date:

Conditions of Approval:

Attached ☐

* Attach Additional Sheets If Necessary

2RP-1502