

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JAN 28 2013

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

nJMWN1303834128

OPERATOR

x x ☐ Initial Report ☐ Final Report

Name of Company Merit Energy Company	Contact Chris Flores
Address 2004 Ave. O Eunice N.M. 88210	Telephone No. 575 - 420-5506
Facility Name WSU 19-2 SWU	Facility Type -SWD Water Station
Surface Owner BLM	Mineral Owner BLM
	API No. Nm.Nm.093772

LOCATION OF RELEASE

API# 30-015-36501

Unit Letter	Section	Township	Range	Feet from	North/South Line	Feet from the	East/West Line	County
	19	18-S	31-E	660	SOUTH	1930	EAST	Eddy

Latitude 32.7247 Longitude -103.9063

NATURE OF RELEASE

Type of Release Produce water	Volume of Release 12-15 bls.	Volume Recovered approx 8 +-
Source of Release From frac tank being fed by injection well	Date and Hour of Occurrence 1-28-13	Date and Hour of Discovery 1-28-18 /6:40 A.M.
Was Immediate Notice Given? Required x x <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not	If YES, To Whom? BLM /James Amos/Terry Gregston OCD / Mike Bratcher	
By Whom? Chris Flores	Date and Hour 1-28-2013 1st call 7:42 a.m. 2nd call 808 a.m. 3rd call 8:19 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes xx <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	

If a Watercourse was Impacted, Describe Fully.*

N.A.

Describe Cause of Problem and Remedial Action Taken.*

Trucking Company inattention, driver quit and relief was not sent in for replacement. Stress importance of communication.

Describe Area Affected and Cleanup Action Taken.*

Area approximately 70 ft x 15 ft wide On location only, around frac tanks. Pick up water that pooled up . Will scrape up all dirt down to clean surface and bring in clean caliche to replace. To haul contaminated dirt to proper disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Chris Flores	OIL CONSERVATION DIVISION	
Printed Name: Chris Flores	Approved by Environmental Specialist	Signed By Mike Bratcher
Title: Production Foreman	Approval Date: FEB 07 2013	Expiration Date:
E-mail Address: chris.flores@meritenergy.co	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: March 7th 2013	Attached <input type="checkbox"/>

2RP-1540

Date: 1-28-2013
575-420-5506

Phone:

* Attach Additional Sheets If Necessary