RECEIVED

FEB 01 2012

Form C-141 Revised October 10, 2003

State of New Mexico

District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410

District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

Energy Minerals and Natural Resources NMOCD ARTESIA Oil Conservation Division 1220 South St. Francis Dr.

Santa Fe, NM 87505

Submit I Copy to appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action													
NMW1304537252							OPERATOR				□ F	inal Report	
Name of Company: Linn Operating 2 (09324							Contact: Joe Hernandez						
		der Hobbs				Telephone No.: 575-738-1739 Facility Type: WaterFlood							
Facility Nai	me: Friess	Federal Batt	ery - Tur	ner B #92	Facility Typ	e: WaterFlood							
Surface Ow	ner: BLM			Mineral C	wner: I								
				LOCA	TION	OF REI	LEASE				47	•	
Unit Letter N	Section 20	·Township 17S	Range 31E	Feet from the 1305		South Line	Feet from the 1350	1	t/West Line County West		Eddy		
Latitude: N 32 49' 30.0" Longitude: W 103 53' 52.9"													
Type of Release: Produced Water Volume of Release: 3 Volume Recovered: 0													
Source of Release: Valve							our of Occurrenc 10:00am				covery:		
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required							If YES, To Whom? M. Bratcher- NM OCD Terry Gregston-BLM						
By Whom? Joe Hernandez							Date and Hour 01/24/2012 3:00pm						
Was a Watercourse Reached? ☐ Yes ☒ No							lume Impacting t	he Watero	course.				
If a Watercou	irse was Imp	oacted, Descri	be Fully.*	:		 							
Describe Cause of Problem and Remedial Action Taken.*: 3" check valve at header just north of injection line, valves blew hole due to corrosion. Shut down transfer pump and closed valves replaced check valve with new.													
Describe Are	Describe Area Affected and Cleanup Action Taken.* : Further remedial action pending												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
Signature: As Associated States of S							OIL CONSERVATION DIVISION						
							Approved by District Supervisor: Signed By Mile Besseles						
Title: Production Foreman A							Approval Date EB 1 4 2013 Expiration Date:						
E-mail Address: jhernandez@linnenergy.com						Conditions of			Attached	Attached			
Date: 02/01/2012 Phone: 575-942-9492 Remediation per OCD													
Attach Addit	Attach Additional Sheets If Necessary Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION ZRD-1559												