<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 811 S. First St., Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

RECEIVED

Form C-141 Revised August 8, 2011

Revised August 8, 2011
Submit 1 Copy to appropriate District Office in with 19.15.29 NMAC.

Oil Conservation Division	Sui
1220 South St. Francis Dr.	NMOC
Santa Fe, NM 87505	

Release Notification and Corrective Action OPERATOR Initial Report Final Report													
Name of Co	(1007	Judah Oil, L		74587				11a		al Report	_Ц	Final Repor	
Address	припу	P.O. Box'56		27501		Contact James B Campanella Telephone No. 575-746-1280.							
Facility Nan	ne	Oxy T-Bone	Fed #1		1	Facility Typ	e SWD						
Surface Own	ner	BLM		Mineral O	wner	BLM API No. 30-015-32122							
LOCATION OF RELEASE													
Unit Letter C	Section 33	Township 18S	Range 31E	Feet from the 660	North/ North	South Line	Feet from the 1980	East/V West	Vest Line	County Eddy			
LatitudeLongitude													
NATURE OF RELEASE													
Type of Release Oil & BS						Volume of Release 180bbls Volume Recovered 170 bbls							
Source of Rel	lease Gun	Barrell				Date and Hour of Occurrence Date and Hour of Discovery 2-5-2013 8:00pm 2-5-2013 9:00 pm						/	
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required						If YES, To Whom?							
		Campanella					our 2-6-2013 8:						
Was a Watero	ourse Read	ched?	Vec 🕅	No.	•	If YES, Vo	lume Impacting th	he Wate	rcourse.				
☐ Yes ☑ No If a Watercourse was Impacted, Describe Fully.*													
· · · · · · · · · · · · · · · · · · ·													
Describe Cause of Problem and Remedial Action Taken.* Valve was closed during equipment repair and wasn't re-opened													
Describe Area Affected and Cleanup Action Taken.* All liquids were contained in fire wall. The fire wall is lined with a 20 mill liner. A vac truck was called when spill was discovered. Oil was skimmed and put back into the holding tanks. Approximately 10 bbls were not recovered. Oil is still seeping through gravel in firewall. We will remove contaminated gravel and replace.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
reducing states of focal laws and of regulations.						OIL CONSERVATION DIVISION							
Signature: SME M													
						Approved by Environmental Specialist By Mily Branches							
Title: Membe					Α	Approval Date: FEB 1 4 2013 Expiration Date:							
E-mail Addres	E-mail Address: judahoil@yahoo.com					Conditions of Approval:			Attached				
Attach Additional Sheets If Necessary Guide							Remediation_per OCD Rule & nidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: arch 14, 2013					1557	