


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Plates to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

| | | | |
|---------------------|---|-------------------------------|--------------|
| Name of Company | COG OPERATING LLC 229/37 | Contact | Pat Ellis |
| Address | 600 West Illinois Avenue, Midland, TX 79701 | Telephone No. | 432-230-0077 |
| Facility Name | Myox 21 State Com #9H | Facility Type | Tank Battery |
| Surface Owner State | Mineral Owner | Lease No. (API#) 30-015-37416 | |

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| M | 21 | 25S | 28E | | | | | Eddy |

Latitude 32 06.616 Longitude 104 05.958

NATURE OF RELEASE

| | | |
|---|---|--|
| Type of Release Produced water | Volume of Release 18bbls | Volume Recovered 15bbls |
| Source of Release FWKO | Date and Hour of Occurrence 02/03/2013 | Date and Hour of Discovery 02/03/2013 12:00 p.m. |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required | If YES, To Whom? | |
| By Whom? | Date and Hour | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |
| If a Watercourse was Impacted, Describe Fully.* | | |
| Describe Cause of Problem and Remedial Action Taken.* A hole developed in the water dump valve at the FWKO. The old valve has been replaced with a new valve. | | |
| Describe Area Affected and Cleanup Action Taken.* Initially 18bbls were released from the water dump valve at the FWKO and we were able to recover 15bbls with a vacuum truck. The entire release was contained inside the lined facility at the Myox 21 State Com #9H Tank Battery. All free fluids have been recovered. Any contaminated gravel has been removed, the liner has been washed, and we have replaced with clean gravel as necessary. This facility has been returned to its prior condition. | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | | |
| Signature: | OIL CONSERVATION DIVISION | |
| Printed Name: Josh Russo | Approved by District Supervisor Signed By | |
| Title: Senior Environmental Coordinator | Approval Date: FEB 22 2013 | Expiration Date: |
| E-mail Address: jrusso@concho.com | Conditions of Approval: | Attached <input type="checkbox"/> |
| Date: 02/14/2013 Phone: 432-212-2399 | | |

* Attach Additional Sheets If Necessary

2RP-1562