


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nJMW 1305630303 OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	OCHO CINCO COM #1H	Facility Type	TANK BATTERY
Surface Owner	FEDERAL	Mineral Owner	
		Lease No.(API#)	30-015-37614

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	8	26S	29E					EDDY

Latitude 32.0623 Longitude 103.9985

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	20bbls	Volume Recovered	19bbls
Source of Release	3" transfer hose	Date and Hour of Occurrence	02/06/2013	Date and Hour of Discovery	02/06/2013 3:00am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A truck driver was transferring fluid at the facility; the truck driver's hose was not secured properly causing the fluid to be released in the lined facility.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 20bbls were released from an unsecured hose connection. We were able to recover 19bbls with a vacuum truck. The release occurred inside the lined facility. All the fluid was contained inside the walls of the tank battery. All free fluid has been recovered. Contaminated gravel has been removed from inside the facility and we have replaced with fresh gravel as necessary. The facility has been returned to its prior condition.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

OIL CONSERVATION DIVISION

Signature:		Approved by District Supervisor:	
Printed Name:	Josh Russo	Signed By	
Title:	Senior Environmental Coordinator	Approval Date:	FEB 25 2013
E-mail Address:	jrusso@concho.com	Expiration Date:	
Date:	02/19/2013	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	432-212-2399		

* Attach Additional Sheets If Necessary

2RP-1564