


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NJMW 1309937035 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	Cimarex Energy	162683	Contact	Terry D. Ainsworth
Address	600 Marienfeld Midland, TX 79701		Telephone No.	(575) 390-1388
Facility Name	Estail AD Fed 2		Facility Type	Gas Well

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE *API 30-015-33336

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	19	24S	26E	2270	North	380	East	Eddy

Latitude 32 12' 13.68" N Longitude 104 19' 29.07 W

NATURE OF RELEASE

Type of Release Condensate & Water	Volume of Release 67	Volume Recovered 30
Source of Release Hole in tank bottom.	Date and Hour of Occurrence 8/10/12 - ???	Date and Hour of Discovery 8/10/12 9:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Terry Gregston	
By Whom? Terry D. Ainsworth	Date and Hour 8/10/12 10:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

oil tank #2 developed a hole in the bottom - called vacuum truck to recover what we could - pulled tank out of service

Describe Area Affected and Cleanup Action Taken.*

While cleaning up contaminated gravel we found that the liner was full of holes - we will drill some core holes to see how deep contamination goes.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Terry D. Ainsworth		Approved by District Supervisor:	Signed By <i>Mike Deane</i>
Title: Senior Production Foreman		Approval Date: APR 09 2013	Expiration Date:
E-mail Address: tainsworth@cimarex.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/27/2013 Phone: 575-390-1388		Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

* Attach Additional Sheets If Necessary

May 9, 2013

2RP-1607