


District I 1625 N. French Dr., Hobbs, NM 88249
District II 811 S. First St., Artesia, NM 88210
District III 1000 Rio Brazos Rd., Aztec, NM 87410
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505



WELL API NO. 30-015-33701
5. Indicate Type of Lease STATE [X] FEE []
6. State Oil & Gas Lease No. B-1969-31

SUNDRY NOTICES AND REPORTS ON WELLS
1. Type of Well: [X] Oil Well [] Gas Well [] Other
2. Name of Operator LEGACY RESERVES OPERATING LP
3. Address of Operator PO BOX 10848, MIDLAND, TX 79702

7. Lease Name or Unit Agreement Name RAPTOR STATE
8. Well Number 1
9. OGRID Number 240974
10. Pool name or Wildcat EMPIRE; YATES-7 RIVERS, EAST

4. Well Location
Unit Letter M : 990 feet from the SOUTH line and 330 feet from the WEST line
Section 21 Township 17S Range 28E NMPM County EDDY

11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3608' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK [] PLUG AND ABANDON [] TEMPORARILY ABANDON [] CHANGE PLANS [] PULL OR ALTER CASING [] MULTIPLE COMPL []
SUBSEQUENT REPORT OF: REMEDIAL WORK [] ALTERING CASING [] COMMENCE DRILLING OPNS. [] P AND A [] CASING/CEMENT JOB []
OTHER: [] [X] Location is ready for OCD inspection after P&A

- [X] All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
[X] Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
[X] A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.

- [X] The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
[X] Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
[X] If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
[X] All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
[X] All other environmental concerns have been addressed as per OCD rules.
[X] Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.
[X] If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE [Signature] TITLE OPERATIONS SUPERINTENDENT DATE 04/24/2013

TYPE OR PRINT NAME KEVIN BRACEY E-MAIL: PHONE: 432-689-5200

For State Use Only

APPROVED BY TITLE DATE

Conditions of Approval (if any):

NOT READY TO BE RELEASED. SEE ATTACHED.
7/26 4/30/13

Well Inspections

API Well No. 30-015-33701-00-00 Owner LEGACY RESERVES OPERATING, LP County Eddy
 Well Name RAPTOR STATE Number 001 Inspect No. ITWG1312053736
 Well Type Oil (Producing) UL STR M - 21 - 17S - 28E Status Plugged (NOT Release) Fac/Proj

Directions

Purpose

Normal Routine Activity

Type

File and Compliance Review

Notification Type

Date Performe 4/30/2013

Date NOV

Date Extension

Date Passed

Compliance Issues

Violation Found?

Significant NC?

Well Idle >1 Year?

Check Global Comp.

Insp/MIT Incident

Failed Items >>>

Write Compliance

Current Type: Status: H Type Status

Respondant Change ONGARD to

240974

N O T E S
 NOT:ready to be released .
 Tubing,rods, flowline, misc piping power drop pole
 and misc junk still op location .

Comply # Incident No Inspector **Tim Gum** Duration

Generate Inspection Reports from [REPORTS] / [INSP]

API Well No. 30-015-33701-00-00 Owner LEGACY RESERVES OPERATING, LP County Eddy
 Well Name RAPTOR STATE Number 001 Inspect No. ITWG1312036899
 Well Type Oil (Producing) UL STR M - 21 - 17S - 28E Status Plugged (NOT Release) Fac/Proj

Directions

Purpose

Normal Routine Activity

Type

Routine/Periodic

Notification Type

Date Performe 4/30/2013

Date NOV

Date Extension

Date Passed

Compliance Issues

Violation Found?

Significant NC?

Well Idle >1 Year?

Check Global Comp.

Insp/MIT Incident

Failed Items >>>

Write Compliance

Current Type: Status: H Type Status

Respondant Change ONGARD to

240974

N O T E S
 Well P&A,d, marker in place. OK . Location currently
 being ripped.Tubing, rods, flowline misc piping and
 junk on location.Power drop pole on location.
 Not ready to release .

Comply # Incident No Inspector **Tim Gum** Duration

Generate Inspection Reports from [REPORTS] / [INSP]