RECEIVED

FEB 1 3 2013

Submit One Copy To Appropriate District State of New Mexico Form C-103 Energy, Minerals and Natural NASCIDE ARTES!A January 20, 2011 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 30-015-34147 District II . OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease **District III** 1220 South St. Francis Dr. STATE FEE 🖂 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 7. Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Townsend 28 DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number 1 1. Type of Well: Oil Well Gas Well Other 9. OGRID Number 2. Name of Operator Devon Energy Production Co. LP 6137 3. Address of Operator 10. Pool name or Wildcat PO Box 250, Artesia, NM 88211 Carlsbad; Morrow South (Pro Gas) 4. Well Location Unit Letter C: 1310 feet from the North line and 1520 feet from the West line Township 22S •Range 27E NMPM County Eddy 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK □ PLUG AND ABANDON REMEDIAL WORK ALTERING CASING □ COMMENCE DRILLING OPNS.□ TEMPORARILY ABANDON. CHANGE PLANS П P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB □ Location is ready for OCD inspection after P&A All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from nonretrieved flow lines and pipelines. ☐ If this is a one-well lease or last remaining well on lease, all electrical service, poles and lines, not to include primary service company equipment, has been removed from lease and well location. When all work has been completed, return this form to the appropriate District office to schedule an inspection. TYPE OR PRINT NAME Denise Menoud E-MAIL: Denise Menoud@dvn.com For State Use Only Conditions of Approval (if any):