Submit One Copy To Appropriate District State of New Mexico	Form C-103
District 1 District 1 Listrict 1 Energy, Minerals and Natural Resources District 1 Energy, Minerals and Natural Resources	Revised August 1, 2011 WELL API NO. 30-015-22101
District II 811 S. First St., Grand Ave., Artesia, NM OIL CONSERVATION DIVISION	5. Indicate Type of Lease
882101220 South St. Francis Dr.District IIISanta Fe, NM 874101000 Rio Brazos Rd., Aztec. NM 87410Santa Fe, NM 87505	STATE FEE X
District IV	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name OLD INDIAN DRAW UNIT
1. Type of Well: XOil Well Gas Well Other Dry Hole	8. Well Number 21
2. Name of Operator $_{s'}$ Chevron USA, Inc.	9. OGRID Number 4323
3. Address of Operator 15 Smith Road	10. Pool name or Wildcat
Midland, TX 79705	INDIAN DRAW; DELAWARE
4. Well Location Unit Letter O : 330' feet from the South line and 2283' feet from the East line	
Section 7 Township 22 S Range 28 E NMPM County Eddy	
11. Elevation (Show whether DR, RKB, RT, GR, etc. 3904' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUB	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR	
PULL OR ALTER CASING	т јов
OTHER: OTHER: D Location is ready for OCD inspection after P&A 3-28-/3	
 All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. 	
X A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
🔯 The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment. [X] Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level,	
If this is a one-well-lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines: production equipment and junk have been removed from lease and well location.	
🕅 All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.) [1] All other environmental concerns have been addressed as per OCD rules.	
 All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- 	
retrieved flow lines and pipelines.	
When all work has been completed, return this form to the appropriate District office to set	nedule an inspection.
SIGNATURE // Regulatory Specialist	DATE 04/29/2013
TYPE OR PRINT NAME Bryan Arrant (Agent for Chevron)E-MAIL: bryan.arrant@chk For State Use Only	e.com PHONE: <u>(405)935-3782</u>
APPROVED BY: <u>Ind</u> June TITLE C.C. Conditions of Approval (if any):	DATE 9/1/13
UKTORELEMSE.	