


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

JMW 323454934

Initial Report Final Report

Name of Company Yates Petroleum Corporation		OGRID Number 25575	Contact Amber Cannon
Address 105 S. 4 TH Street		Telephone No. 575-748-1471	
Facility Name Dolores AIL Federal #2 (Livingston Ridge)	API Number 30-015-26548	Facility Type Well	
Surface Owner Federal	Mineral Owner Federal	Lease No. NM-65418	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	14	22S	31E	1980'	South	430'	East	Eddy

Latitude 32.3896 Longitude 103.74089

NATURE OF RELEASE

Type of Release Produced Water; Crude Oil	Volume of Release 40 B/PW; 100 B/O	Volume Recovered 10 B/PW; 15 B/O
Source of Release Poly pipe rupture	Date and Hour of Occurrence 8/12/2013	Date and Hour of Discovery 8/12/2013
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 8/12/2013	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* A poly pipe ruptured		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 75' X 50'. Spill is approximately 100 yards north of cattle guard where CR29 intersects, approximately 50 feet east of lease road at tin horn. The flow line valves were shut off, leak was isolated, and Dolores water pump was shut off. There was some overspray that reached vegetation northwest of the tin horn and across the lease road (this area was sprayed with micro blaze). A crew was called to do initial clean-up of the area, and all excavated soils will be disposed of at an approved NMOCD facility. Vertical and horizontal delineation samples will be taken and sent to a NMOCD approved facility. Depth to Ground Water: >100' (approximately 150', Section 11, T22S-R31E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: <i>Amber Cannon</i>	Approved by District Supervisor: Signed By <i>Mike Bratcher</i>	
Printed Name: Amber Cannon	Approval Date: AUG 22 2013	Expiration Date:
Title: Environmental Regulatory Agent	Conditions of Approval:	
E-mail Address: acannon@yatespetroleum.com	Attached <input type="checkbox"/>	
Date: Tuesday, August 20, 2013 Phone: 575-748-4111	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

* Attach Additional Sheets If Necessary

September 22, 2013

2RP-1857

1 of 2