

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED
NOV 26 2013
State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. 260737	Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: Nash Draw 8 SWD #1	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-41351

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County: Eddy
L	8	24S	30E	2075	South	630	West	

Latitude N 32.231646 Longitude W 103.910656

NATURE OF RELEASE

Type of Release: Produced water and crude oil	Volume of Release: 10 bbls crude oil and 4,357 bbls produced water	Volume Recovered: 7 bbls crude oil and 4,207 bbls produced water.
Source of Release: Gun-barrel over flow	Date and Hour of Occurrence 11/22/13 at 3:00 a.m.	Date and Hour of Discovery: 11/22/13 at 3:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency number 104 and the BLM	
By Whom? Tony Savoie	Date and Hour 11/22/13 at 8:16 a.m., BLM 11/22/13 at 8:19 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Water was being transferred into the gun-barrels and the facility storage tanks to supply water to the Aquilla rig #8. a valve was discovered closed on the transfer line to the storage tanks causing the gun-barrels to overflow inside the impervious containment. The containment overflowed into the adjoining impervious containment around the skim tank and onto the ground. The valve alignment was corrected and vacuum trucks started recovering the spilled produce water.

Describe Area Affected and Cleanup Action Taken.* The spill impacted the area around the facility SWD the adjoining well pad for the PLU-192, the new pad around the ND-8 SWD well, Rawhide road and adjoining pasture area. Approximately 50,600 sq.ft. of well pad, tank battery pad and lease road along with approximately 12,000 sq.ft. of pasture area, the spill happened during a rain, sleet and snow event. The areas impacted may be more or less than the area described due to the weather conditions during and after the spill event, also the volume loss may be subject to correction based on the remediation findings. All of the free standing fluid which was produced water and rain water was picked up with vacuum trucks and put back into the disposal or transferred off-site. The containment around the gun-barrel tanks held approximately 3225 bbls., the containment around the skim tank held approximately 382 bbls. all of this was recovered along with approximately 600 bbls in the pasture area. The spill area will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: <i>Mike Benison</i>	
Title: Waste Management and Remediation Specialist		Approval Date: NOV 26 2013	Expiration Date:
E-mail Address: tasavoie@basspet.com		Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached <input type="checkbox"/>
Date: 11/25/13	Phone: 432-556-8730	2RP-2081	

* Attach Additional Sheets If Necessary

December 26, 2013