

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1000 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

FEB 05 2014

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report

☒ Final Report

nHMP 1406939926

Name of Company	COG OPERATING LLC 229137	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Graham Cracker 16 State #003H	Facility Type	Tank Battery

Surface Owner State	Mineral Owner	Lease No. (API#) 30-015-41633
---------------------	---------------	-------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	16	26S	28E					Eddy

Latitude 32.04922

Longitude 104.09016

NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Oil	155bbls	150bbls
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Oil tank	02-03-2014	02-03-2014 08:00am
Was Immediate Notice Given?	If YES, To Whom?	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	Mike Bratcher - NMOCD	
By Whom? Michelle Mullins	Date and Hour 02-04-2014 1:50pm	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The oil tank ran over due to transport trucks did not show up. Called trucking company and told them they must be on time.

Describe Area Affected and Cleanup Action Taken.*

Initially 155bbls of oil were released due to transport trucks not showing up on time. We were able to recover 150bbls of oil with vacuum trucks. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:	Approved by District Supervisor:	
Printed Name: Robert Grubbs Jr.	Approval Date: 3/10/14	Expiration Date: NA
Title: Senior Environmental Coordinator	Conditions of Approval: Final	
Email Address: rgrubbs@concho.com	Attached <input type="checkbox"/>	
Date: 02-05-2014	Phone: 432-661-6601	

* Attach Additional Sheets If Necessary

2RP 2194