


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1400247338

Name of Company		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
COG OPERATING LLC 229/37		Contact	Robert McNeill		
Address 600 West Illinois Avenue, Midland, TX 79701		Telephone No.	432-230-0077		
Facility Name Down South State Com #004H		Facility Type	Tank Battery		
Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-37256		

LOCATION OF RELEASE

Unit Letter P	Section 19	Township 26S	Range 28E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.02223

Longitude 104.11917

NATURE OF RELEASE

Type of Release Oil and produced water	Volume of Release 15bbls of oil 25bbls of produced water	Volume Recovered 0bbls of oil 0bbls of produced water
Source of Release FWKO	Date and Hour of Occurrence 12-08-2013	Date and Hour of Discovery 12-08-2013 3:30pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Michelle Mullins	Date and Hour 12-10-2013 07:12am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A gasket on a FWKO failed. Replaced the gasket to prevent a recurrence.

Describe Area Affected and Cleanup Action Taken.*

Initially an estimated 15bbls of oil and 25bbls of produced water were released from a gasket failure on a FWKO. We were unable to recover any fluids. The spill area is located on the location and the adjacent pasture. Concho will have the spill area sampled to delineate any possible contamination from the release and we will present a work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.	Approved by District Supervisor:	Signed By: Mike Bratcher	
Title: Senior Environmental Coordinator	Approval Date: JAN 02 2014	Expiration Date:	
E-mail Address: rgrubbs@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 12-19-2013	Phone: 432-661-6601		

* Attach Additional Sheets If Necessary

Remediation per OCD Rule &
Guidelines. SUBMIT REMEDIATION

PROPOSAL NO LATER THAN:

Feb. 2, 2014

2RP-2129