


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

NJMW 1402326326

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian Ltd. <i>192463</i>	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Indian Hills Unit #39	Facility Type	Well Location

Surface Owner	BLM	Mineral Owner		API No.	30-015-32103
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	16	21S	24E	1690	South	1701	East	Eddy County, NM

Latitude N 32.47646° Longitude W 104.50610°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	4 bbls oil, 106 bbls produced water	Volume Recovered	0 bbls
Source of Release	6" steel production flow line	Date and Hour of Occurrence	01/07/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD, JeanMarie Warren-NMOCD, James Amos-BLM, Jennifer Van Curen-BLM		
By Whom?	Jennifer Gilkey, BBC International	Date and Hour	12/30/2013 @ 12:45 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A leak in a 6" steel production flow line caused 4 bbls of oil and 106 bbls of produced water to leak onto the ground. No fluids were recovered and the line was repaired.

Describe Area Affected and Cleanup Action Taken.*
The affected area is approximately 20' x 400' on and off location. Remediation will be completed in accordance with a plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Christopher Jones	Approved by District Supervisor:	Signed By <i>Mike Bratcher</i>
Title:	HES Specialist	Approval Date:	JAN 23 2014
E-mail Address:	Christopher.Jones@oxy.com	Expiration Date:	
Date:	1/9/14	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	(575) 628-4121	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

* Attach Additional Sheets If Necessary

February 23, 2014
2RP-2155