

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis  
Santa Fe, NM 87505

**RECEIVED**  
JAN 15 2014  
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.  
**NMOC D ARTESIA**

Form C-141  
Revised August 8, 2011

**Release Notification and Corrective Action**

*njmw 1402855518* OPERATOR  Initial Report  Final Report

Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU-387H Tank Battery	Facility Type: Exploration and Production
Surface Owner: U.S.A. <i>↓</i>	Mineral Owner: U.S.A.
API No. 30-015-41185	

*State or Fed(?)* LOCATION OF RELEASE

Unit Letter D	Section 18	Township 25S	Range 31E	Feet from the 526	North/South Line North	Feet from the 418	East/West Line West	County: Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	--------------

Latitude N 32.136122 Longitude W 103.824399

**NATURE OF RELEASE**

Type of Release: Crude oil and produced water	Volume of Release: 29 bbls crude oil and 6 bbls produced water	Volume Recovered: 20 bbls crude oil and 5 bbls produced water
Source of Release	Date and Hour of Occurrence: 1/5/14 at 7:00 a.m.	Date and Hour of Discovery: 1/5/14 at 7:00 a.m.
-Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Delayed report to Mike Bratcher NMOCD BLM on 1/5/14 at 12:30 p.m.	
By Whom? Tony Savoie	Date and Hour 1/7/14 at 11:36 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
The valves on the process valves were misaligned and the flare scrubber dump failed to operate properly. The system over pressured and fluid went out the flare line vent. The system was restored to normal operations.

Describe Area Affected and Cleanup Action Taken.\*  
Approximately 247,860 sq. ft. of pasture area was lightly misted by the release, fluid visible on the vegetation but not on ground surface. Approximately 23,726 sq. ft. of pasture was more heavily impacted by the release, the vegetation was covered and there was 6 inches to 1 inch of saturation on the soil. There was a berm around the flare system that contained some of the fluid; approximately 25 bbls total fluid was recovered from the bermed area. The heavily impacted vegetation was washed down with soap, water and micro-blaze mixture. The spill will be remediated in accordance to the NMOCD and BLM recommended guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	Approved by Environmental Specialist: Signed By <i>Mike Bratcher</i>	
Title: Waste Management and Remediation Specialist	Approval Date: <b>JAN 28 2014</b>	Expiration Date:
E-mail Address: tasavoie@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>1/14/14</i> Phone: 432-556-8730	Remediation per OCD Rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b>	

\* Attach Additional Sheets If Necessary

*February 28, 2014*

*2RP-2164*