


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

nHMP1409234972

**OPERATOR**

Initial Report  Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 <sup>TH</sup> Street		Telephone No. 505-748-1471
Facility Name Ohkay SWD #3	API Number 30-015-35164	Facility Type Battery

Surface Owner State	Mineral Owner State	Lease No. VO-6711
------------------------	------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter N	Section 6	Township 25S	Range 30E	Feet from the 990	North/South Line South	Feet from the 2310	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.15463 Longitude 103.92149

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 90 B/PW	Volume Recovered 90 B/PW
Source of Release Produced Water Tank	Date and Hour of Occurrence 12/31/2013 PM	Date and Hour of Discovery 12/31/2013 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD District II	
By Whom? Robert Asher/YPC Environmental	Date and Hour 12/31/2013, E-mail	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

Describe Cause of Problem and Remedial Action Taken.\*  
Pump did not start, caused tank to overflow. Vacuum truck(s) called.

Describe Area Affected and Cleanup Action Taken.\*  
An approximate area of 30' X 75' (inside lined, bermed battery). All produced water was picked up. **Depth to Ground Water: >100' (approximately 250' per the ChevronTexaco trend map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. With enclosed information, Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Robert Asher	Approved by District Supervisor:	
Title: Environmental Regulatory Agent	Approval Date: <u>4-2-14</u>	Expiration Date: <u>NA</u>
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: <u>Final</u>	Attached <input type="checkbox"/>
Date: Tuesday, January 21, 2014 Phone: 575-748-4217	<b>Like approval by</b>	

**BLM**

2RP-2244

\* Attach Additional Sheets If Necessary