


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1000 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

*HTMP 1407641879*

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Stonewall 9 Fee #001H	Facility Type	Tank Battery
Surface Owner	Private	Mineral Owner	
		Lease No. (API#)	30-015-40925

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	09	19S	26E					Eddy

Latitude 32.66874 Longitude 104.39442

**NATURE OF RELEASE**

Type of Release	Volume of Release	Volume Recovered
Produced water	50bbls	50bbls
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
90 on feed line to KO	02-13-2014	02-13-2014 09:00 am
Was Immediate Notice Given?	If YES, To Whom?	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	Mike Bratcher - NMOCD	
By Whom? Michelle Mullins	Date and Hour	
	02-14-2014 07:32 am	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
A 90 on the feed line to the water KO corroded and cracked. Replaced with a coated 90.

Describe Area Affected and Cleanup Action Taken.\*  
Initially 50bbls of produced water were released due to a crack in a 90. We were able to recover 50bbls of produced water with a vacuum truck. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert Grubbs Jr.		Approved by District Supervisor: <i>[Signature]</i>	
Title: Senior Environmental Coordinator		Approval Date: 3-17-14	Expiration Date: NA
E-mail Address: rgrubbs@concho.com		Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>
Date: 02-21-2014	Phone: 432-661-6601		

\* Attach Additional Sheets If Necessary

*22P-2216*