


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

nHMP1409135761

**OPERATOR**

Initial Report  Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 105 S. 4 <sup>TH</sup> Street		Telephone No. 575-748-1471
Facility Name Checker BIC Federal Com: #4-H	API Number 30-015-40962	Facility Type Battery

Surface Owner Federal	Mineral Owner Federal	Lease No. NM-94614
--------------------------	--------------------------	-----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	9	19S	31E	660	North	330	East	Eddy

Latitude 32.68029 Longitude 103.86636

**NATURE OF RELEASE**

Type of Release Crude Oil	Volume of Release 10 B/O	Volume Recovered 8 B/O
Source of Release Production tank	Date and Hour of Occurrence 1/3/2014; AM	Date and Hour of Discovery 1/3/2014; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A.	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Equalizer valve on EQ line closed to tank to be produced into. Vacuum truck called.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 5' X 45' (inside bermed and lined battery). Vacuum truck called to pick up oil (2 B/O remained entrained in gravel) impacted material removed and taken to an NMOCD approve facility. New gravel to be put back down. <b>Depth to Ground Water: &gt;100' (225', ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: &gt; 1000', SITE RANKING IS 0. Based on remaining oil recovered, impacted gravel removed, battery is lined and liner intact, Yates Petroleum Corporation requests closure.</b>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

**OIL CONSERVATION DIVISION**

Signature:	Approved by District Supervisor:	
Printed Name: Robert Asher	Approval Date: 4-1-14	Expiration Date: NA
Title: NM Environmental Regulatory Supervisor	Conditions of Approval: Final	
E-mail Address: boba@yatespetroleum.com	Attached <input type="checkbox"/>	
Date: Tuesday, January 21, 2014 Phone: 575-748-4021	Like approval by	

\* Attach Additional Sheets If Necessary

**BLM**

2RP-2240